ETEC 223


NC/CNC


NC (Numerical Control)

- NC is not a machining process.
- NC is the operation of the machine tool by a series of coded instructions.
- The code consists of alphanumeric data that are translated into pulses of electric current.
- NC Program....
 - Instruct servos when to start, in what direction to move, and how far to move.
 - Control feed rate, cutter speed, coolant flow and tool changes.

DNC & CNC


- DNC
 - Used to identify two different NC methods
 - Direct Numerical Control
 - Distributed Numerical Control
 - For large mfg. Situation
- Two DNCs





CNC (Computer Numerical Control)

Five units of a CNC




HAAS VF-4 CNC Mill





Positioning with CNC


Cartesian Coordinate System




Z axis is assigned to the spindle motion








X, Y & Z Coordinates




Tool positioning methods

Incremental & Absolute positioning




Incremental (G91)

Absolute (G90)



Work Coordinate System (Zero Part Set)

- ◆ G54 G59 & G110 G129
 - Allow us to set a (0,0) for work piece.
 - Temporary move of machine (0,0) points.



Programming with G & M Codes

- G & M Codes
 - G-Codes
 - Preparatory Codes
 - Tool & Table movements
 - M-Codes
 - Miscellaneous Codes
 - Control of spindle, direction, coolant,....

Modal & Non-Modal Commands

Modal

Call it out once, stay active until another code from its group appears.

Non-Modal

- Use only once.
- Have to call out every time you want to use it.
- If group # on a G & M code sheet is 00, then it is a non-modal command.

CNC Programming I (Word Address Programming)

Programming Language Terminology

- Character
 - Alphanumeric or Punctuation mark
 - N, G, ;, 1, 9
- Addresses
 - Letter that describes the meaning of the numerical value following address
 - X, Y, Z, G, M,....
 - G00, X -3.75,...
 - G & X; addresses
 - 00 & -3.75; characters
- Words
 - Address + Number(s)
 - G90 (=absolute positioning)
- Block/Line
 - One or more Words

- Block: Contains one or more words
 - N20 G90 G00 X-2.5 Y3.75 S1000;
 - O; Program Number
 - N; Sequence or Line Number
 - G; Prep. Code. Relates to movement of machine
 - M; Miscellaneous Code. Relates to control of machine
 - X, Y, Z, I, J, K, P, Q, R; Movement of axis.
 - Must contain DECIMAL point
 - F; Feed rate (IPM)
 - Must contain DECIMAL point
 - S; Spindle speed (RPM)
 - T; Tool number (1 to 10 for HAAS Mini Mill)
 - D; Tool diameter offset (use with G code)
 - H; Tool height offset (use with G code)

Program

- A sequence of blocks
 - %
 - 00001
 - (Tool list)
 - (T10-Dowel pin)
 - (T1-2.5 Face cutter)
 - (T2-1.0 End mill)
 - N001 G0 G90 G80 G40 G17
 - N002 G91 G28 Z0.
 - N003 G28 Y0.
 - N004 T10 M06 (Dowel pin)
 - N005 G00 G90 G54 X.1875 Y-1.5
 - N006 G43 H10 Z2.
 - N007 Z.2
 - N008 G1 Z-.5 F20.
 - NO09 MO0
 - • • •
 - N090 M30
 - %


Start-up Block

S & F

- To find S (=rpm) value:
 - Rpm = (CS * 4) /Dia.
- To find F (=ipm) value:
 - For Milling;
 - ◆ IPM = Rpm * IPT * N
 - IPT is table value (Table 10A, p. 786)
 - N is number of teeth or inserts
 - For Drilling;
 - ◆ IPM = Rpm * IPR
 - IPR is table value (Table H-3, p. 373)
 - For Tapping;
 - ◆ IPM = Rpm * IPR
 - Select numbers between 200 and 1000 for Rpm.
 - IPR is the value of pitch

Locate X & Y (Math. for CNC prog.)

To determine the Sides



Known Angle a:

A/C = Sin a

B/C = Cos a

A/B = Tan a

Known Angle b:

B/C = Sin a

A/C = Cos a

B/A = Tan a

Locate X & Y (Math. for CNC prog.)

To determine the Angles

 $b = Tan^{-1}(B/A)$

